

## \*\*\* SCI PRODUCT CUT SHEET \*\*\*




**TOP VIEW** 



**FRONT VIEW** 

PARTS LIST			
ITEM	QTY	PART NUMBER	
1	1	POWERMOUNT-9000 - SP	
2	1	EPDM GASKET-1.500 x 1.875	
3	2	FASTENER 14x1-1/8 SS CAP W/ WASHER	
4	1	FASTENER M8 x 1.25 x 35MM ROD	
5	1	8mm x 1.25 SERRATED FLANGED HEX NUT	



**RIGHT VIEW** 

## NOTES:

- FOR CLARITY THIS DRAWING IS NOT TO SCALE.
- 2.
- CONTACT THE MANUFACTURER FOR RECOMMENDED LAYOUTS, SPACING AND ADDITIONAL DETAILS.
  INSTALLATION MUST BE COMPLETED WITH THE MANUFACTURERS WRITTEN SPECIFICATIONS AND INSTALLATION INSTRUCTIONS. 3.
- THESE DRAWINGS ARE SUBJECT TO CHANGE WITHOUT NOTICE.



## 4800 METALMASTER WAY - McHENRY, IL 60050

PHONE: 800.815.7652 WEBSITE: WWW.SOLARCONNECTIONS.COM FAX: 815.455.4367 E-MAIL: INFO@SOLARCONNECTIONS.COM

## **POWERMOUNT-9000S - ASSY**

DRAWN BY:	rhoeffleur	T
DATE:	4/22/2018	K
SCALE:	N.T.S.	V
ΜΔΤΕΒΙΔΙ ·		l''

THE INFORMATION HEREIN IS CONFIDENTIAL AND PROPRIETARY AND S NOT TO BE DISCLOSED OR DELIVERED TO THIRD PARTIES WITHOUT THE PRIOR WRITTEN CONSENT OF SOLAR CONNECTIONS NTERNATIONAL, INC.